Sixty-seventh Legislative Assembly of North Dakota

FIRST ENGROSSMENT with Senate Amendments ENGROSSED HOUSE BILL NO. 1059

Introduced by

13

14

Energy and Natural Resources Committee

(At the request of the Public Service Commission)

- 1 A BILL for an Act to amend and reenact subsection 1 of section 49-23-06 of the North Dakota
- 2 Century Code, relating to requiring an excavator to call 911 upon damage to a facility that
- 3 releases any flammable toxic or corrosive gas.

4 BE IT ENACTED BY THE LEGISLATIVE ASSEMBLY OF NORTH DAKOTA:

5 SECTION 1. AMENDMENT. Subsection 1 of section 49-23-06 of the North Dakota Century
6 Code is amended and reenacted as follows:

7	1.	a.	If any damage occurs to an underground facility or its protective covering, the
8			excavator shall notify the operator as soon as reasonably possible. When the
9			operator receives a damage notice, the operator shall dispatch, as soon as
10			reasonably possible, personnel to the damage area to investigate. If the damage
11			results in the escape of flammable, toxic, or corrosive gas or liquid, the excavator
12			shall:

(1) Call 911 immediately; and

(2) Notify the pipeline operator immediately.

15	<u>b.</u>	If the damage endangers life, health, or property, the excavator responsible for
16		the work shall take immediate action to protect the public and property and to
17		minimize the hazard until arrival of the operator's personnel or until emergency
18		responders have arrived and taken charge of the damaged area.

b.c. An excavator shall delay backfilling in the immediate area of the damaged
underground facilities until the damage has been investigated by the operator,
unless the operator authorizes otherwise. The repair of damage must be
performed by the operator or by gualified personnel authorized by the operator.

Sixty-seventh Legislative Assembly

6

- e.d. An excavator is guilty of a class A misdemeanor if the excavator damages an
 underground facility or its protective covering and knew or reasonably should
 have known the damage occurred and:
 (1) The excavator does not notify the operator as soon as reasonably possible
- 4 (1) The excavator does not notify the operator as soon as reasonably possible;
 5 or
 - (2) The excavator backfills in violation of subdivision bc.